

Fork Wrap Lights Installation Instructions

Make sure motorcycle is OFF when installing your Fork Lights


- 1) Test each light prior to installation by touching Black wire to battery neg. & Yellow wire to battery pos.
- 2) Thoroughly clean and dry fork are where light is to be mounted.
- 3) With 3M Promoter Pad, wipe area on fork that the tape on the back of the strip will adhere to. Allow to dry.
- 4) Working on only one fork side at a time, warm the LED Fork Light (picture #1) using a heat gun or hot hairdryer. Make sure you warm the entire length of the strip making it pliable enough to wrap around fork tube.
- 5) Before peeling the red strip over the tape, do a test-run by wrapping the light around the fork tube to make sure there will be no obstructions during the actual mounting (Picture #2).
- 6) Peel red tape from back of light strip (you may need to re-warm the strip to keep it pliable).
- 7) Wrap around fork tube in desired location. Tape will hold the light in place while you connect the 2 ends of the zip tie (picture #3). Make sure the wires are not pinched behind the zip tie when tightening. Tighten Zip tie. Once tight, trim off excess end of zip tie.
- 8) Refer to your model owner's manual for left and right turn signal wire. On most bikes turn signal wires can be found inside of headlight bucket.



Picture #1



Picture #2



Picture #3

